

Invalidez de garantía



Alteración al producto

Pieza limada



Pieza golpeada



ENGINEERING

Invalidez de garantía




Alteración al producto

Pieza barrenada



Pieza forzada




ENGINEERING

Invalidez de garantía



Producto no distribuído por Cloyes




ENGINEERING

Invalidez de garantía



Producto no distribuído por Cloyes



ENGINEERING

Invalidez de garantía



## Uso de pegamento en tensores




ENGINEERING

Invalidez de garantía



## Instalación inadecuada del kit



Inapropiada revisión de run out o "cabeceo" genera desgaste o arrastramiento en el "canto" del engrane.



ENGINEERING

Invalidez de garantía



## Instalación inadecuada del kit




Aceite contaminado  
Rebabas, suciedad, lodo,  
entre otros.

ENGINEERING

Invalidez de garantía



## Instalación inadecuada del kit



No instalar el kit de acuerdo a  
especificaciones técnicas  
(secuencia, torque, cambio del kit  
por completo, reemplazo de  
tornillos, entre otros).

1	Cylinder head cover	6	No.3 engine mount rubber and No.3 engine joint bracket
2	Crankshaft pulley lock bolt	7	Engine front cover
3	Crankshaft pulley	8	Front oil seal
4	Water pump pulley		
5	Drive belt auto tensioner		

9	Chain tensioner	14	Oil pump chain guide
10	Tensioner arm	15	Oil pump sprocket
11	Chain guide		
12	Timing chain		
13	Oil pump chain tensioner	16	Oil pump chain
		17	Crankshaft sprocket

ENGINEERING